

25X1
TO : [REDACTED]
UNIT :
EXT :
DATE : 16 NOV 60

TOP SECRET

CLASSIFIED MESSAGE 0 NOV 60 502

25X1
FROM : DIRECTOR
CONF : OPS (1-2-3-4)
INFO : S/C (5)
25X1
CLZ
TOR: 2258Z 16 NOV 60

ROUTINE	ROUTINE	PRIORITY	INITIALS
ROUTINE	ROUTINE	OPERATIONAL IMMEDIATE	INITIALS

775445

25X1
[REDACTED]

CITE

4976

- A. GF 60-5
- B. HICKHAM 16/2110Z
- 25X1 C. [REDACTED] IN COMMISSION
- D. NEW SUBJECT. 378 EXPERIENCED SAME SITUATION ON FERRY FLIGHT THAT OCCURRED
- 25X1 AT [REDACTED], TAIL PIPE RUMBLE. ENGINE CHANGED DUE TO A PIECE OF SAFETY
- 25X1 WIRE PASSING THROUGH OIL PUMP.

END OF MESSAGE

25 YEAR RE-REVIEW

25X1
[REDACTED]

25X1
[REDACTED]

TOP SECRET

[Handwritten signature]

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy No.